

Customer: DeKalb County

Location: Doraville, GA

Time & Duration: 30 Days

Technical Description: Service Call

Technologies: CPU314

Reference: Dekalb County 14-421 / 1.1.1



Service call

Customer has a performance problem with existing Siemens CPU314

Solution

- Replacement of a Siemens CPU with a newer version of 314
- Installation of 64 SD Card to load the program back to the PLC.
- Took offline copy and converted it to new hardware and downloaded it to PLC.
- Deleted one byte in DB2 to get it to compile and download.

MEXICO

INP Mexico S.A de C.V
Fray Junipero Serra #2450
Suite 501
Pabellón Cooperativo Juriquilla
76230 Queretaro
Mexico

Tel. +52 442 3930703
mx.inp@actemium.com

USA

INP North America Inc.
11390 Old Roswell Rd.
Suite 126
Alpharetta, GA 30009
USA

Tel. +1 678 527-1400
Fax +1 678 527-1410
us.inp@actemium.com

CANADA

INP Canada Inc.
2275 Upper Middle Rd E
Suite 101
Oakville, Ontario L6H 0C3
Canada

Tel. +1 678 527-1400
ca.inp@actemium.com